





Express Mail Label No. EL985154150US Inventor(s): Raymond A. Lia and Joshua L. Scott Atty. Docket No. 702-105 Atty. Joel Stettenheim Telephone: (315) 425-9000










Express Mail Label No. EL985154150US Inventor(s): Raymond A. Lia and Joshua L. Scott Atty. Docket No. 702-105 Atty. Joel Stettenheim Telephone: (315) 425-9000



F16 3D






FIG. 4

Express Mail Label No. EL985154150US Inventor(s): Raymond A. Lia and Joshua L. Scott Atty. Docket No. 702-105 Atty. Joel Stettenheim Telephone: (315) 425-9000

Recalibration module

Instructions Sub-routine pr 422

Slock Removal Sub-routine pr 424

Zero-Point Sub-routine pr 424

Serva Control Values Recalibration pr 430

Sub-routine

Serva Control Module pr 416

F16. 5

Express Mail Label No. EL985154150US
Inventor(s): Raymond A. Lia and Joshua L. Scott
Atty. Docket No. 702-105
Atty. Joel Stettenheim
Telephone: (315) 425-9000

